Map ID MAP FINDINGS

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EDR ID Number

528 219 BRIGHTWATER CT/BKLYN NY Spills S102141639 ESE 219 BRIGHTWATER COURT N/A

1/2-1 BROOKLYN, NY

0.815 mi. 4305 ft.

Relative: SPILLS:

HigherName:219 BRIGHTWATER CT/BKLYNActual:Address:219 BRIGHTWATER COURT

9 ft. City, State, Zip: BROOKLYN, NY

Spill Number/Closed Date: 9005106 / 1995-06-07 Facility ID: 9005106

 Facility ID:
 9005106

 Facility Type:
 ER

 DER Facility ID:
 98914

 Site ID:
 113343

 DEC Region:
 2

Spill Cause: Equipment Failure

Spill Class: C3 2401 SWIS: 1990-08-08 Spill Date: Investigator: **FINGER** Referred To: Not reported Reported to Dept: 1990-08-08 Not reported CID: Water Affected: Not reported

Spill Source: Institutional, Educational, Gov., Other

Spill Notifier: Other
Cleanup Ceased: 1995-06-07
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False

Remediation Phase: 0

Date Entered In Computer: 1990-08-08
Spill Record Last Update: 2003-01-31
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 999

Contact Name: Not reported

DEC Memo:

Remarks: "SPILL CONTAINED IN TANK & BOILEROOMS, PETRO TANK CLEANERS HAVE VAC

TRUCK ON SCENE TO DO CLEAN UP."

All Materials:

Site ID: 113343 Operable Unit ID: 945589 Operable Unit: 01 Material ID: 436169 Material Code: 0001A Material Name: #2 fuel oil Not reported Case No .: Material FA: Petroleum 2500.00 Quantity: Units: G

Recovered: .00

Oxygenate: Not reported